



N.T.A. WATER RESOURCES BRANCH
BORE DATA SHEET

RN004181

8 m N of Paddys Soak
 W bank of Hanson River

(2)

NAME DUD	INDEX No. 27/121
LOCALITY Stirling	REG. No. 4181
DEPTH 100'	FILE No.
CASINGS	PERFORATIONS SCREENS
LOCATION 27 / 10 / 31.5 E14.0 N	SURFACE LEVEL R.L.
	B.M. LEVEL R.L.
	DATUM
CONTRACTOR.	DRILLER.
	DATE STARTED.
	DATE FINISHED.

WATER				STRATA SECTION			
AQUIFERS	DEPTH FEET	CASING	AQUI SEC.	STRATA			
DEPTH STRUCK				clayey sand all the way			
AQUIFER THICKNESS							
STANDING WATER LEVEL							
PUMP TEST G.P.H.							
DRAWDOWN LEVEL							
PU LEVEL							
DURATION OF TEST HOURS							
R.L. S.W.L.							
WATER TEMPERATURE °C							
TRANSMISSIBILITY							
STORAGE COEFF.							
ANALYSES							
BINOMIAL CLASSIFICATION							
T. D. S.							
CONDUCTIVITY							
TOTAL HARDNESS							
CHLORIDE							
BICARBONATE							
CARBONATE							
SULPHATE							
NITRATE							
FLUORIDE							
SODIUM							
POTASSIUM							
CALCIUM							
MAGNESIUM							
REG. ANAL. No.							
EQUIPMENT.							
REMARKS.							