

THE NORTHERN TERRITORY OF AUSTRALIA

N.T.A. 181

Control of Waters Ordinance

SF53-2

245456.

Regulation 8.

IN. 33/77

FINAL STATEMENT OF BORE

RN. 10,271

From	To	Description of Strata	Name of Bore -									
		DRILLED INTO GRANITE	DUD BORE									
			Name of Property -									
			KURUNDI									
			Description of Property -									
			PASTORAL.									
			Name of Owner -									
			H. V. LEONARD,									
			Name of Contractor -									
			STATION PLANT,									
			Name of Miller -									
			O. WIERIET,									
Location of Bore (or supply sketch on back hereof) -			Date of Commencement -									
1.2 Miles												
(a) <table border="1"> <tr> <td>(N)</td> <td>NE</td> <td rowspan="4">of (b) HOMESTEAD</td> </tr> <tr> <td>S</td> <td>SE</td> </tr> <tr> <td>E</td> <td>NW</td> </tr> <tr> <td>W</td> <td>SW</td> </tr> </table>			(N)	NE	of (b) HOMESTEAD	S	SE	E	NW	W	SW	Date of Completion -
(N)	NE	of (b) HOMESTEAD										
S	SE											
E	NW											
W	SW											
(b) Circle appropriate direction: (c) Use known point such as existing bore, homestead, outstation, etc.			1952									
Additional information of interest about the bore -			Total Depth -									
INFORMATION: GATHERED IN FIELD SURVEY			60'									
			Particulars of Casing -									
			Particulars of Perforations or Screens -									
			Water	1st Supply	2nd Supply	3rd Supply						
Samples of strata and water supplies have been* will be* left at the following trading place -			Struck at									
			Standing Water Level									
			Pumping Supply: G.P.H.									
Signature: C. SLYTH			Duration of Pump Test									
*Strike out which does not apply.			Water Level During Test									
For office use only -			Quality: Good, Fair or Bad									



RN010271

